

[별첨 1]

★측정결과 [2017년 04월 25일]

시료 번호	측정 지점	측정결과			초과 여부
		유량 (ℓ/min)	총 유량 (ℓ)	측정농도(f/cc) (기준:0.01f/cc)	
1	덕은리 857-13,857-7,613-2 부지경계	12.1	2420	0.001	미만
2	덕은리 857-13,857-7,613-2 부지경계	12	2460	0.000	미만
3	덕은리 857-13,857-7,613-2 부지경계	11.8	2419	0.000	미만
4	덕은리 857-13,857-7,613-2 부지경계	12	2520	0.001	미만
5	덕은리 857-13,857-7,613-2 위생설비	12	420	0.002	미만
6	덕은리 857-13,857-7,613-2 음압기 배출구1	12	420	0.003	미만
7	덕은리 857-13,857-7,613-2 작업장 주변(실외)	12	1260	0.001	미만
8	덕은리 857-13,857-7,613-2 음압기 배출구2	12.2	427	0.005	미만
9	덕은리 857-13,857-7,613-2 폐기물 반출구	12	420	0.004	미만
10	덕은리 857-13,857-7,613-2 폐기물 보관지점	12	420	0.003	미만

[별첨 2]
★측정 지점 위치도(도식도) [2017년 04월 25일]



-  작업장주변 (실외)
-  부지경계선
-  폐기물 반출구
-  폐기물보관지점
-  위험설비
-  유입기 배출구

[별첨 3]
[2017년 04월 25일]

석면비산 농도측정 관련 사진



#1 부지경계



#2 부지경계



#3 부지경계



#4 부지경계



#5 위생설비



#6 음압기 배출구1

[별첨 3]
[2017년 04월 25일]

석면비산 농도측정 관련 사진



#7 작업장 주변 (실외)



#8 음압기 배출구2



#9 폐기물 반출구



#10 폐기물 보관지점