


[별첨 1]

★측정결과 [2017년 04월 24일]

시료 번호	측정 지점	측정결과			초과 여부
		유량 (ℓ/min)	총 유량 (ℓ)	측정농도(f/cc) (기준:0.01f/cc)	
1	덕은리872-2,871-5 부지경계	12	2460	0.001	미만
2	덕은리872-2,871-5 부지경계	11.8	2419	0.001	미만
3	덕은리872-2,871-5 부지경계	12	2460	0.001	미만
4	덕은리872-2,871-5 부지경계	12.1	2480.5	0.001	미만
5	덕은리872-2,871-5 위생설비	12	420	0.003	미만
6	덕은리872-2,871-5 음압기 배출구1	12	420	0.004	미만
7	덕은리872-2,871-5 폐기물 반출구1	11.6	406	0.003	미만
8	덕은리872-2,871-5 폐기물 보관지점	11.6	406	0.003	미만
9	덕은리872-2,871-5 음압기 배출구2	12.1	423.5	0.004	미만
10	덕은리872-2,871-5 폐기물 반출구2	12.2	427	0.003	미만

[별첨 2]

★측정 지점 위치도(도식도) [2017년 04월 24일]



[별첨 3]  
[2017년 04월 24일]

### 석면비산 농도측정 관련 사진



#1 부지경계



#2 부지경계



#3 부지경계



#4 부지경계



#5 위생설비



#6 음압기 배출구1

[별첨 3]  
[2017년 04월 24일]

### 석면비산 농도측정 관련 사진



#7 폐기물 반출구1



#8 폐기물 보관지점



#9 음압기 배출구2



#10 폐기물 반출구2